

New District Pond

Ladies & Gentlemen:

An additional pond, indentified as #48 on the Ponds Maintenance Report, has recently been added to the work load of the Harmony Field Services staff.

This pond is located off the lower end of the north-east side of *Feathergrass* in the “O” community (otherwise known as “*Waterside*”) – see attached graphic.

To my knowledge, this pond has never been identified in any District Engineer documentation or presentation available to the Harmony CDD Board of Supervisors.

Confirmation is needed that this pond is indeed part of the Harmony Stormwater Management System, and is accordingly the responsibility of the District to maintain.

It is therefore required and requested that District Engineer, Steve Boyd, provide immediate updates to any and all affected documents so that appropriate action is taken.

With regards,

David Farnsworth


Harmony CDD Board

Supervisor Seat-1

New District Pond

Google Maps

28°11'28.2"N 81°08'13.9"W



Imagery ©2020 Maxar Technologies, U.S. Geological Survey, Map data ©2020 200 ft